



Report Number: QIP-ASI124451

26 Apr., 2012 Audit Date : Expiry Date : 25 Apr., 2013

This report is issued by Focus Technology Co., Ltd. (Made-in-China.com) and the supervising inspectorate (SGS-CSTC Standards Technical Services Co., Ltd.) to confirm that:

Company Name : Xuzhou Kaixin Electronic Instrument Co., Ltd.

徐州市凯信电子设备有限公司

Showroom : http://kaixin.en.made-in-china.com

: Kaixin Mansion, C-01, Economic Development Zone, Xuzhou, Jiangsu, Address

China

: Ultrasound scanner **Product**

has been on site audited for the Following Scope of Activity

1. General Information

2. Quality Management System and Product Certification

3. Production Capacity & Quality Control

4. Photos



General Comments:

Xuzhou Kaixin Electronic Instrument Co., Ltd. is a manufacturer with 138 employees; it was established in 1997, located in Kaixin Mansion, C-01, Economic Development Zone, Xuzhou, Jiangsu, China. The buildings occupy an area

of more than 6,500 square meters. Xuzhou Kaixin Electronic Instrument Co., Ltd. has its own brand " have passed ISO9001:2008 and ISO13485:2003 certifications, and already have obtained EC certificates for Ultrasonic Diagnostic Instruments and RoHS certificate for Ultrasound diagnostics.

Sign for and on behalf of

SGS-CSTC Standards Technical Services Co., Ltd.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any face of the proposition of the content of the safely and the safely and

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: <code>CN.Doccheck@sgs.com</code>

Page No.: 1 of 14



SUPPLIER ASSESSMENT REPORT

Audited Company	Xuzhou Kaixin Electronic Instrument Co., Ltd. 徐州市凯信电子设备有限公司
Audited Site:	Kaixin Mansion, C-01, Economic Development Zone, Xuzhou, Jiangsu, China
Representative of Audited Company:	Ms. Sting Shi / Foreign trading staff

Consigner of Assessment	Made-in-China.com		· 學 計 性 愛 ·
Audit Type		TAIXIN GROUP	
	☐ Re-audit		
Valid Date	From 26 Apr., 2012 to 25 Apr., 2013	Verify Report	www.sgs.com
Auditor	Simon Gao	Reviewed by	Roger Wang

CONTENTS

\boxtimes	Part A	: General	Information
-------------	--------	-----------	-------------

Section 1: Company Overview Section 2: Human Resources

Part B: Foreign Trade Capacity

Section 1: Export Overall Situation Section 2: Export Business Capacity Section 3: Supplier Management

Section 4: After-sales Service Capacity

Part C: Product Research & Development Capacity

Section 1: Product Research & Development Capacity

□ Part D: Quality Management System and Product Certification

Section 1: Quality Management System(s) and Product Certification

□ Part E: Production Capacity & Quality Control

Section 1: Production Capacity Section Section 2: Production Process Control

Section 3: Company Development / Expansion Plan

Part F: Financial Position

Section 1: Financial Data

Section 2: Key Performance Indications

Section 3: Banking

Section 4: Product Insurance

Part G: Working Environment & Energy Saving

Section 1: Working Environment

Section 2: Energy Savings and Emission Reduction

Part H: Photos

Section 1: Photos of Documents Section 2: Photos of Company

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions if any factoripeur, oele responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest nt of the law.

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

Page No.: 2 of 14

中国・江苏・南京・中山南路315号瑞华大厦19楼

19/F, Ruihua Building, No.315, Zhongshan South Road, Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 t (86-25) 58075282 f (86-25) 83407773 邮编:210001

SGS No: QIP-ASI 1 2 4 4 5 1





Part A: General Information

Section 1: Company Overview

1.1 Legal Validity				
Does the company have a valid business license?		Registration Number	320301000008981	
Year of established	03 Apr., 1997	Valid Date	02 Apr., 2020	
Registered address	Kaixin Mansion, C-01, Economic D	evelopment Zone	, Xuzhou, Jiangsu, China	
Actual address	Kaixin Mansion, C-01, Economic D	evelopment Zone	, Xuzhou, Jiangsu, China	
Is the annual review done by local authority (Industrial & Commercial Bureau)?	The business was reviewed in yea	r 2012.		
Registered capital	RMB 10,000,000			
Name of legal representative	Mr. Guozheng Bu			
Business scope	Special item: Manufacture of Class III 6823 Medical Ultrasonic Instruments and relevant equipments. Normal item: Sales of electronic products(medical equipments according to permit license), computer; Self-management and agency all kinds of goods and technology import and export business (except the state limited enterprise management or prohibit)			
1.2 Basic Information				
Contact person	Mr. Shasen	Email	info@kxele.com	
Phone number	0086-516-87732932 0086-516-87733758	Fax number	0086-516-87732932 0086-516-87792848	
URL/Web address	www.kxele.com			
Company type				
Type of ownership	☐ Limited Company ☐ Public (Company 🗌 Jo	int Venture	
	☐ State-Owned ☐ Private	Owner	holly foreign-owned enterprises	
Subsidiary company	No subsidiary company			
Products manufactured / sold scope	Ultrasound scanner			
1.3 Company Building Information				
According to: ☐ Land certificate ☐ Lease agreement The land occupies 4,144.9 square meters.				
The buildings occupy 6,520.62 square meters.				

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the content of the content of the content of the intervention only and within the limits of Client's instructions, or a transaction from exercising all their rights and obligations under the transaction documents any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

**Renting To check the supplementation of the content or appearance of the supplementation or appearance of


uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 3 of 14

> 19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001





Section 2: Human Resources



•	· · ·	
Code	Department	Number of employees
Α	General Manager	1
В	Supervisor representative	1
С	Admin Dept. and Human Resource Dept.	6
D	Quality Control Dept.	5
Е	Finance Dept.	5
F	Vice General Manager	1
G	Technology Dept.	22
Н	Supply Dept.	4
I	Production Dept.	27
J	Quality Dept.	4
K	Foreign Trade Dept.	15
L	Domestic Sales Dept.	38
М	After Service Dept.	9
	Number in total:	138

2.3 Key Staff

-io not out in the control of the co				
Title	Full name	Education	Working experience for this trade / total experience	
General Manager	Mr. Guozheng Bu	Junior college	/ 22 years	
Technology Dept. Manager	Mr. Kai Kang	Junior college	/ 23 years	
Sales Dept. Manager	Mr. Siyuan Tang	Junior college	/ 22 years	

Remark: Above information of key staff was based on interview with company representative.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any factoripary cole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents by unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest

nt of the law. uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

Page No.: 4 of 14

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773



Part D: Quality Management System and Product Certification

1.1 Quality Management System and Product Certification

Has the company obtained a valid certificate for its quality management system? Such as ISO9001, QC080000 and

ISO9001:2008 Certificate

No.: 04712Q10041R4M

Scope: The Design, Development, Production and Service of KX2600 Series Full Digital B Mode Ultrasonic Diagnostic Instruments, KX280 Series Full Digital B Mode Ultrasonic Diagnostic B Mode Ultrasonic Diagnostic Instruments, KX5000 Series Full Digital B Mode Ultrasonic Diagnostic Instruments, KX2000 Series Full Digital B Mode Ultrasonic Diagnostic Instruments.

Issued by Beijing Hua Guang Certification of Mdeical Devices Co., Ltd.

Valid until 17 Jan., 2015 ISO13485:2003 Certificate

No.: 04712Q10000035

Scope: The Design, Development, Production and Service of KX2600 Series Full Digital B Mode Ultrasonic Diagnostic Instruments, KX280 Series Full Digital B Mode Ultrasonic Diagnostic B Mode Ultrasonic Diagnostic Instruments, KX5000 Series Full Digital B Mode Ultrasonic Diagnostic Instruments, KX2000 Series Full Digital B Mode Ultrasonic Diagnostic Instruments.

Issued by Beijing Hua Guang Certification of Mdeical Devices

Co., Ltd.

Valid until 17 Jan., 2015

Is product certification done in terms of selling designation (UL for US, CCC for China, CE for Europe ...) at the company?

- Product certification list? if any
- Sample of product certification, if any (at least one of key products)?
- III) Copy of product certification sample (1-5 key products, if any)?

EC Certificate

No.: G1 11 12 52731 007

Product: Ultrasonic Diagnostic Instruments

Directive: 93/42/EEC on Medical Devices (MDD), Annex II

excluding(4) (Devices in Class IIa, IIb or III)

Valid from: 12 Jan., 2012 Valid until: 11 Jan., 2017

This certificate was issued by TUV

RoHS Certificate

No.: G4 10 12 52731 006 Product: Ultrasound diagnostics

Model(s): Full Digital Mechanical Sector Scanning Ultrasonic

Diagnostic Instruments(MSU1, MSU2) Parameters: Rated voltage: 12V DC

Tested according to:

1. European Directive 2002/95/EC(RoHS)

2. IEC 62321, Edition 1.0 2008-12 Electro Technical

Products-Determination of levels of six regulated substances

(lead, mercury, cadmium, hexavalent chromium.

Polybrominated biphenyls, polybrominated dipheny ethers)

Issue date: 27 Dec., 2010 This certificate was issued by TUV

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any factoribating cole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations to the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest of the law.

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

Page No.: 5 of 14





Part E: Production Capacity & Quality Control

Section 1: Production Capacity



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any factoribating cole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations to the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest nt of the law.

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 6 of 14

> 19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001



1.2 Products Situation (Top three Product Categories)					
Product Category	Capacity in Top Month	Average Capacity	Total in 2011		
	398 units	312 units	3,746 Units		
Description: B Mode Ultrasonic Diagnostic Instruments					

1.3 Main Facilities

1.0 Wall I delities					
Picture	Facility name	Brand or Country/Region of origin	Quantity		
	Residual voltage tester	China	1		
Control of the contro	Leakage current measurer	China	1		
	Earth resistance tester	China	1		

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the content of the content

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

Page No.: 7 of 14

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773



Control of the state of the sta	High-Pop tester	China	2
VMS1410A	Image measuring apparatus	China	1
	Oscillograph	Japan	6
	Tissue mimicking ultrasound Phantom	China	5
	Vibration tester	China	1
高温老化例行试验室	High temperature Burn-in Room	China	1

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the content of the content of the content of the intervention only and within the limits of Client's instructions, or a transaction from exercising all their rights and obligations under the transaction documents any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

**Renting To check the supplementation of the content or appearance of the supplementation or appearance of

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 8 of 14

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773

SGS No: QIP-ASI 1 2 4 4 5 1





Section 2: Production Process Control

2.1 Pro	2.1 Production Process Control				
Item	Content	Observations /Comments			
1	Are the environmental conditions, such as tidiness and cleanliness being controlled and suitable for the operation performed?	✓ Very tidy☐ Normal☐ Need to improve☐ Very poor			
2	Are the necessary items /documents provided at appropriate location and under control?	 ☑ Work Instructions /procedures ☑ Workmanship standard /acceptance ☐ Golden sample /Approval sample ☐ Product picture ☐ Verbal by workshop director 			
3	Are written instructions available for incoming material inspections /testing? Is the relevant record maintained?	☐ Has instructions and uniformly followed☐ Has instruction but no written records☐ Materials checked by storage staff			
4	Are written inspections /testing instructions available for finished products? Is the relevant record maintained?	 ☑ Have instructions and uniformly followed ☐ Have instruction but no written records ☐ Finished product checked by packing staff 			
5	What type of inspection is used for finished products?	 □ Random inspection □ Visual inspection □ Function inspection ☑ 100% inspection ☑ Visual inspection ☑ Function inspection 			
6	Are non-conforming units clearly marked/ segregated to prevent accidental dispatch?	☑ Marked and segregated☐ Segregated but not marked clearly☐ Not found on site			
7	How are the non-conforming units handled?	 ☐ Repaired and re-inspection ☐ Picked out ☐ Used under control ☐ Disuse 			

Section 3: Company Development / Expansion Plans

3.1 Company Development / Expansion Plans			
Item	Company Development Action(s)	Timeframe	
1	Plan to attend Hospitalar 2012 in Sao Paulo, Brazil.	22~25 May, 2012	
2	Plan to attend FIME 2012 in Miami Beach, Florida, America.	08~10 Aug., 2012	
3	Plan to attend MEDICA 2012 in Dusseldorf, Germany.	14~17 Nov., 2012	

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the content of the content of the content of the intervention only and within the limits of Client's instructions, or a transaction from exercising all their rights and obligations under the transaction documents any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

**Renting To check the supplementation of the content or appearance of the supplementation or appearance of

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 9 of 14

> 19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001



Part H: Photos

Section 1: Photos of Documents

1.1 Photos of Documents

Description: Business License



Description: Export License



Description: ISO9001 Certificate



Description: Land Certificate



Description: Production Permit License



Description: ISO13485:2003 Certificate



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any factoriphing cole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations to the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest transaction uccession: To re

authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com
Page No.: 10 of 14

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼

邮编:210001 t(86-25)58075282 f(86-25)83407773



Description: Trademark Registration Certificate



Description: EC Certificate



Description: Utility Model Patent Certificate (13PCS)



Description: RoHS Certificate



Description: Design Patent Certificate(5PCS)



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the Company sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document by unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest

of the law. uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 11 of 14

> 19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001



Section 2: Photos of Company

Description: Company Building



Description: Company Hall



Description: Office



Description: Company Reception



Description: Office



Description: Material Warehouse



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms and conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the company sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents by unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

**Rention: To check the authorized to the content of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

uthenticity of testing /inspection report & certificate, please contact us at Page No.: 12 of 14 at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t(86-25) 58075282 f(86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773



Description: Warehouse



Description: Process



Description: Test Room



Description: Workshop



Description: Burn-in Room



Description: Test Instruments



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the Company sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document by unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest action docume of the law.

at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com uthenticity of testing /inspection report & certific Page No.: 13 of 14

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773

t (86-25) 58075282 f (86-25) 83407773



Description: Showroom





Description: Showroom



Description: Showroom



Description: Showroom



Description: Showroom



-- End of the Report --

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and to adjust accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any face of the safely and to the safely and the safely an nt of the law.

uthenticity of testing /inspection report & certificate, please contact us at Page No.: 14 of 14 ate, please contact us at telephone: (86-755)83071443, or email: <u>CN.Doccheck@sgs.com</u>

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t(86-25) 58075282 f(86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773